Plane Crash Cause Speculated

Santo Domingo, Dominican Republic - Aviation officials speculated Monday that a Dominican Airways DC-9 may have banked too steeply when it tried to return to the airport Sunday night after an engine failed. The plane spun into the Caribbean, killing all 102 persons aboard. The DC-9 had just tak-

en off from the Las Americas Airport in Santo Domingo for San Juan when pilot Eduardo Tomeu, a Cuban, reported one engine had failed. The plane fell when he was attempting a right turn at low altitude about three miles from the airport.